

INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS®, INC. IS NOT AUTHORIZED. ©Texas Association of REALTORS®, Inc., 2004

CONC	ERNING THE PROPERTY AT Hunt, TX			
A. DESCRIPTION OF ON-SITE SEWER FACILITY ON PROPERTY:				
(1)	Type of Treatment System: Septic Tank Aerobic Treatmen	t	Unknown	
(2)	Type of Distribution System: Ressure distribu	tion	Unknown	
	Approximate Location of Drain Field or Distribution System: Behind house on the lower le		Unknown	
(4)) Installer:		Unknown	
	Approximate Age: 1998		Unknown	
B. MA	AINTENANCE INFORMATION:			
(1)	Is Seller aware of any maintenance contract in effect for the on-site self yes, name of maintenance contractor:	ewer facility?	es UNo	
	Phone: contract expiration date:			
(2)	Approximate date any tanks were last pumped?	r 2019		
(3)) Is Seller aware of any defect or malfunction in the on-site sewer facili If yes, explain:	ty?	es UNo	
(4)	Does Seller have manufacturer or warranty information available for i	review?	es UNo	
C. PL	ANNING MATERIALS, PERMITS, AND CONTRACTS:			
(1)	(1) The following items concerning the on-site sewer facility are attached: planning materials permit for original installation final inspection when OSSF was installed maintenance contract manufacturer information warranty information			
(2)	(2) "Planning materials" are the supporting materials that describe the on-site sewer facility that are submitted to the permitting authority in order to obtain a permit to install the on-site sewer facility.			
(3) It may be necessary for a buyer to have the permit to operate an on-site sewer facility transferred to the buyer.				
(TXR-14	407) 1-7-04 Initialed for Identification by Buyer, and Selle	MOUND	Page 1 of 2	
1968, 3825 I Lindsey Rob	Lake Austin Blvd, Austin TX 78703 Phone: (512)4 bersum Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallar	Fax: TX 75201 www.lwolf.com	125 Deer Haven	